

CERTIFICATE OF COMPLIANCE

Certificate Number 20190430-E203454
Report Reference E203454-19990720
Issue Date 2019-APRIL-30

Issued to: KISEONG CABLE INC
219 Jangpyeong-Ro Saha-Gu
Busan 604-836 KOREA

**This certificate confirms that
representative samples of**

COMPONENT - APPLIANCE WIRING MATERIAL
Refer Addendum page for Models/Product

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.


Standard(s) for Safety:
Additional Information:

UL 758, Appliance Wiring Material
See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20190430-E203454
Report Reference E203454-19990720
Issue Date 2019-APRIL-30

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

STYLES SINGLE-CONDUCTOR THERMOPLASTIC-INSULATED WIRE

1007; 1011; 1013; 1015; 1017; 1019; 1020; 1021; 1022; 1024; 1026; 1027; 1028; 1030; 1032; 1039;
1053; 1054; 1055; 1056; 1057; 1058; 1059; 1060; 1061; 1099; 1283; 1284; 1497; 1498; 1499; 1500;
1569; 1581; 1617; 1647; 1865; 10269; 10616; 11028



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

